

400 North IMPROVED

Bountiful

Construction Update April 6, 2017



Overall Project Update:

Crews have installed most curb, gutter, medians, and driveways between the eastern project limits and 200 West. Earlier this week crews began the same work between 200 West and 500 West and will continue these activities through next week.

Area residents are reminded that driveway and on-street parking is not available while crews complete this work. Once driveways have been installed, please allow 7 days for the concrete to cure and reach its strength.

Side Street Closures at 300 West and 350 West:

*On Monday, April 10, 300 West and 325 West will be closed at 400 North through April. Crews will be reconstructing the tie-ins between these side streets and 400 North.

Closure Impacts:

- Driveway access will be closed to corner properties. Residents will need to park at an alternate location during this time.
- Area residents can expect heavy noise, construction machinery, and lighting during this work.

*Suggested Detour Map: 200 North or 500 West.



All paving and work activities are subject to change due to weather, material, equipment, or utility delays.

We appreciate your help in keeping work enclosures free from vehicles as we continue to do work in the area. For questions regarding your property or project activities, please contact us at 888-556-0232, ext. 2.


Bountiful City Park Repairs:

Crews will be replacing sidewalk in front of the park in mid April. During this work sidewalk access will be closed and fenced off. Pedestrians and park visitors will need to use caution near the work zone and obey all posted signage.

Landscape Repair:

As warmer weather approaches, crews anticipate working on landscape repairs along the corridor in mid-to-late April.

Have questions regarding your property?
Contact us at 888-556-0232, ext. 2.



UDOT Region One, 166 Southwell Street, Ogden, UT 84404

400north@utah.gov